
16' X 32' RECTANGLE 4' RADIUS



ADDITIONAL NOTES

Rough excavation should be 2" deeper in each instance.

EXCAVATION NOTES

3. The ideal water level should be to the middle of the skimmer opening(s). 2. Soil to have minimum bearing capacity of 2000 P.S.F.
3. Locate top of pool at least 6" above surrounding land elevation.
4. See 'Overdig Detail' for excavation around pool.
5. Fill volds under base of panets and tamp well.
6. Backfill with non-expansive material.

uocument ID: HF5100, Hydra Standard Panel Layout Drawing Rev Date: 12:62005 Rev Level: A

GENERAL NOTES

Dimensions are from inside pool panels. hese are finished dimensions ready for the liner.

THIS DOCUMENT IS FOR ILLUSTRATIVE PURPOSES ONLY.

The dealer or contractor who sells or installs your pool is an independant contractor and is not an agent of the Manufacturer. The construction methods illustrated here are suggestions and apply construction. Proper installation is the responsibility of the dealer/builder/contractor. only to normal ground conditions. There may be additional precautions and/or methods of

œ	COP			21	ω ι	2 1	2	_	7	ALO TITE	J	I	I	G	F	ш	D	B	A
	COPING LAYOUT			+		HP204L	_	HP206A		OF MA	4'	4'	4	ω	ω	4'8"	3'4"	32'	16'
5 * * 5	TUOY			BRACE	4'R PANEL	4' PANEL (LIGHT) 2' PANEL	4' PANEL	6' PANEL (A/G)	6' PANEL	OF MATIERIALS PART DESCRIPTION	u	P	z	S	-	<u>₹</u>	3	_	×
12 * * 12						(LIGHT)		(A/G)	1	S	٠			•			∞	14'	<u>ට</u>
												1				1		PE	
12 * * 12												-G				A	١	PERIMETER	ı
*	NO.									OVER		<u>+</u>		<u></u>	_ -	1	ļ	ᆽ	
∞ are in the state of the s	NO DIVING WARNING	6" TO 8" DEEP WHI	UNDISTURBED EARTH	MATERIAL BACK	USE NON-EXPAN	POLYMER BRACE	. .		APPROX 4" DEEP	OVERDIG DEIMI		<u></u>	т-	+5	7- —	T		89'2"	ı
ATTENTION DEALER A ATTENTION DEALER A TE syour responsibility is delivered to the po- responsibility in STALL ACCORDINI	D DIVI	" DEEP 11 P 3/8" REBAR WHERE NEEDED AROUND PERIMETER OF BOND BEAM				####				AIL		J					ŀ		S
A TECHTION DEAL ERBUILDER: It is your responsibility to ensure it is delivered to the pool owner and are properly installed. "NO DIVING" WARNIN INSTALLED IN NO ACCORDING TO NSI A DANG! AND DIVING SHALLOW ON SHALLOW TO SHEEL	NG WA	3/8" REBAR BED AROUND —			\langle					- 2' OVERDIG		İ	\						SQ. FO
	NO DIVING WARNING			~	<i>//</i>	<u></u>	Ů					T	\			<u></u>		GALLONS	FOOTAGE
that the "NO DIVING" GEND GARDEN INJURY TER MANAGEM INJURY GEND GARDEN INJURY AQUAGENIE	- TOX IS		2' VERMICULITE OR SAND BOTTOM		VINYL LINER	PANEL	BOLVMER	- BENC	ALUMINUM			+		_			ŀ		H
MUST BE REAS ATTIONS ATTIONS ARTIONS ARTICLES ARTICLE			СИLITE		LINER	ĺ		BENCHMARK	3			<u>×</u>						17751	512
→ W S												+			_ _		- 1	-	

JAN 2012 CORNERSTONE









20126-PWH

Copyright © 2012 by Hydra Pools