

- 1. Place pole in corner of hopper
- 2. Use a level on the pole to level side to side
- 3. Measure over from long wall from bead track
- 4. Mark Deck

